



BUREAU  
VERITAS

# CHANNELLOCK INC.

1306 SOUTH MAIN STREET MEADVILLE, PA 16335 USA

This is a multi-site certificate, additional site(s) are listed on the next page(s)

Bureau Veritas Certification Holding SAS – UK Branch certifies that the Management System of the above organisation has been audited and found to be in accordance with the requirements of the management system standards detailed below

## ISO 9001:2015

*Scope of certification*

The design and manufacture of pliers and resale of specialty hand tools for the automotive, industrial, and commercial markets

Original Cycle Start Date:	16-November-2016
Expiry date of previous cycle:	18-November-2019
Certification / Recertification Audit date:	30-August-2019
Certification / Recertification cycle start date:	10-December-2019
Subject to the continued satisfactory operation of the organization's Management System, this certificate expires on:	16-November-2022

Certificate No. : US013942      Version: 1      Issue Date: 10-December-2019





Certification Body Address: 5th Floor, 66 Prescott Street, London, E1 8HG, United Kingdom

Local Office: 16800 Greenspoint Park Drive, Suite 300S, Houston, TX 77060, USA

Further clarifications regarding the scope of this certificate and the applicability of the management system requirements may be obtained by consulting the organisation.







BUREAU VERITAS

# CHANNELLOCK INC.

## ISO 9001:2015

### Scope of certification

Site Name / Location	Site Address	Site Scope
CHANNELLOCK INC.	1306 SOUTH MAIN STREET MEADVILLE, PA 16335 USA	Administration, Design, Production
CHANNELLOCK INC. - Bldg 1	11372 Mercer Pike MEADVILLE, PA 16335 USA	

Bureau Veritas Certification

Certificate No. : **US013942**

Version: **1**

Issue Date:

**10-December-2019**



Certification Body Address: 5th Floor, 66 Prescott Street, London, E1 8HG, United Kingdom

Local Office: 16800 Greenspoint Park Drive, Suite 300S, Houston, TX 77060, USA

Further clarifications regarding the scope of this certificate and the applicability of the management system requirements may be obtained by consulting the organisation.

